


Details


Public Involvement Meeting

Repair Pier Concrete




Heavy Concrete Deterioration with Exposed Rebar


Overlay Concrete Deck over Machinery Area



Deteriorating Concrete Has Been Patched Multiple Times



Replace Steel Grid Deck



Numerous weld repairs on broken/missing bars. Grid Deck requires continuous repairs.

Replace Median Barrier and Stringers




Severe Deterioration under Median Barrier Corroded Stringer

Refurbish Machinery



Mechanical components showing corrosion and evidence of leaking seals.


Repair Fender System



Corroded Sheet Piling

Deteriorated & Missing Timbers and Rubber Rails

Clean & Paint Structural Steel



Paint System is Failing on Bascule Span