




Safety: Bicycle and Pedestrian

The lack of facilities and high vehicle speeds lower the desire to walk or bike on US 51.



Bus stops and shared-use paths bring multimodal traffic to US 51

Pedestrians and bicyclists would need to **travel along the shoulder** for most of the US 51 corridor

Lack of facilities makes it less safe to walk or bike along US 51



All pedestrian and bicycle crashes resulted in an injury.

